
## ONLY TO BE USED IN EMERGENCIES OR SAMPLE STATION INSTALLATIONS



## APPROVED TAPPING METHOD:

- 1. ROMAC DOUBLE STAINLESS STEEL STEEL SADDLE TAP
- 2. SEE STD DWG W-1 FOR TAPPING DETAILS

## NOTE: CURB STOP BOX SETTINGS

- A. ONLY CAST IRON CURB STOP BOXES
- SHALL BE USED.
- B. LID SHALL BE AT FINISHED GRADE.
- C. LID SHALL HAVE "WATER" IMPRINTED ON LID.

ITEM NO.	NO. REQD.	DESCRIPTION
1	1_	CAST IRON CURB STOP BOX
2	3	1" BRASS PACK JOINT ASSEMBLY
3	1	1" x reqd. length —— USE IRON PIPE SIZE POLYETHYLENE HDPE (250 PSI)
4	1	1" x REQD. LENGTH (STOPPING AT PROPERTY LINE)— USE PIPE SIZE GALV. OR IRON PIPE SIZE POLYETHYLENE PIPE
5	1	1" BRASS CURB STOP WITH PACK JOINT ASSEMBLY.



CITY OF COEUR D'ALENE STANDARD DRAWING

1" - 2" CURB STOP Chia Boxley C.I. BOX ASSEMBLY

APPROVED BY:

10/1/24 DATE:

DWG NO.

W-5